




**LEA**  
PROFESSIONAL

# LEA Connect 4.0.4.3 Firmware Update Readme

**\*\*\*NOTE – This firmware file is for all 1500 watt models.**

## Firmware update instructions:

- The firmware updater is located in the WebUI in the top right corner. Click the Hamburger Menu, Choose File, and then Update Firmware.
- Click 'Choose Firmware File' – **unzip the firmware update file** and select .tar.xz file (BS-4-0-4-3.tar.xz.enc) then click “update amps”
  - **NOTE 1:** This firmware file works for 1504 & 1504D LEA Connect Series Amplifiers.
  - **NOTE 2:** All amplifiers on the same network will be updated.
- The shark fin will turn magenta during the update process, please do not turn off or power cycle the amplifier until the firmware update is complete.
- Once the shark fin is blue and the LCD screen is illuminated, the firmware update process is complete.
- While not required, it is recommended to power cycle the amp with the power cord after the firmware update is complete.

To Confirm the update was successful, click on the  and then Amp Settings. Scroll down to Device Information and you should have the following Firmware versions:

### **1504 and 1504D Models:**


Firmware Version: 4.0.4.3

Power Supply Version: 4.0.4.2


Amp1234 Version: 4.0.4.1

### **CS Touch 0.1.00.435**


Click the Hamburger Menu



Click 'Firmware Update'



1. Choose file: BS-4-0-4-3.tar.xz.enc
2. Click 'Update Amps'



## **Features and Improvements in 4.0.4.3:**

### **WebUI and General Updates**

- Added Quick Setup mode for ease of setup for some basic applications

### **CS Touch**

- Added ability to set static IP. CS Touch Firmware update to 0.1.00.435 required for this functionality

### **Sharkware Specific Updates**

- Added User Access Control of the WebUI to lock out specific parameters

### **Amplifier Updates**

- None.