




LEA
PROFESSIONAL

LEA Connect - ADSP 4.0.4.0 Firmware Update Readme

*****NOTE - This firmware file is for all 350, and 700 watt models Advanced DSP Versions (-ADSP).**

Firmware update instructions:

- The firmware updater is located in the WebUI in the top right corner. Click the Hamburger Menu, Choose File, and then Update Firmware.
- Click 'Choose Firmware File' – **unzip the firmware update file** and select .tar.xz file (SS-4-0-4-0.tar.xz.enc) then click “update amps”
 - **NOTE:** All amplifiers on the same network will be updated.
- The shark fin will turn magenta during the update process, please do not turn off or power cycle the amplifier until the firmware update is complete.
- Once the shark fin is blue and the LCD screen is illuminated, the firmware update process is complete.
- While not required, it is recommended to power cycle the amp with the power cord after the firmware update is complete.
- 350W and 700W models will take ~5 minutes to update firmware

To Confirm the update was successful, click on the  and then Amp Settings. Scroll down to Device Information and you should have the following Firmware versions:


350W and 700W -ADSP Models:

Firmware Version: 4.0.4.0


Power Supply Version: 4.0.4.0

Amp1234 Version: 4.0.4.0


Click the Hamburger Menu



Click 'Firmware Update'



1. Choose file: SS-4-0-4-0.tar.xz.enc
2. Click 'Update Amps'



Features and Improvements in 4.0.4.0:

WebUI and General Updates

- Added Quick Setup mode for ease of setup for some basic applications

Sharkware Specific Updates

- Added User Access Control of the WebUI to lock out specific parameters

Amplifier Updates

- None